## BRUHAT BANGALORE MAHANGARA PALIKE

### Inspection Report

| | | |
|---|---|---|
| 1 | Name Of Work: | Providing and laying HDPE water line in Channappa Garden and Sundarnagar in JP Park ward 17 |
| 2 | Administration Approval & Date | JC/RRN/AS/2247/2013-14 Dtd: 17.09.2013 |
| 3 | Technical Sanction Estimate No. & Date | CE/RRN/TS/294/2013-14 Dtd: 18.09.2013 |
| 4 | Estimate Amount | 49,90,000/- |
| 5 | Job Code No. | 017-14-000015 |
| 6 | P-Code | P-2201 |
| 7 | Agreement No and Date: | EE/RRND/Agmt/238/13-14 Dtd: 07.02.2014 |
| 8 | Work order Number & Date | EE/RRND/WO/238/13-14 Dtd: 07.02.2014 |
| 9 | Contract Amount as per Agreement | Rs. 53,38,571/- |
| 10 | Bill Amount | Rs. 49,14,052=91 |
| 11 | B.R No. & Date | 254/14-15 Dtd: 30.06.2014 |
| 12 | Agency | K Shivakumar |
| 13 | M.B. Number & Page No. of Measurement records | 120/13-14 Page No 11943 to 11948 |
| 14 | Date of Inspection | 06.09.2017 |
| 15 | Enclosures | 2 Number of photos taken during inspection |
| 16 | Inspection Report | I have Inspected the abov sit along with the Conserned person, as per EE(RRND) Letter No EE (RRN) PR/414/A/17-18 Dated 1-9-2017. It is observed that the Items indicated in the xerox copy of MB/XL sheets are not susceptible for measurements, as the nature of work is laying HDPE water Line, and asphalting of Road work has been done after Completion of above work; as such the photos taken during the execution of work have been scrutinized and Inspected; it appears that the above work has been done. This has a reference to the NOC Issued by Lokayukta vide Letter No LOK/INV(J)/CT/Crime 60/2014 Dated 1-8-2017 |

6/9/2017

(R. Sathyanarayana)
Inspection Report Officer.
R. SATHYANARAYANA
INSPECTION OFFICER

EE (RRN) Division, RR Nagara Zone.
ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ರಾಜರಾಜೇಶ್ವರಿನಗರ ವಿಭಾಗ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಬೆಂಗಳೂರು -

Scanned by CamScanner